

Printer

Supported protocols

TCP/IP

Printer model	Note
Canon	
MP960	*2, *7
MP950	*2
MP810	*2
MP800	*2
MP780	*2
MP760	*1
MP750	*2
MP600	*2, *7
MP510	*2
MP500	*2
MP460	*2
MP450	*2
MP370	
MP180	*2
MP170	*2
MP160	*2
MP130	
MP110	
MF8180C	
iP8500	
iP6700D	
iP6600D	
iP6320D	
iP6310D	
iP6220D	
iP6210D	
iP5300	*7
iP5200	
iP4300	*7
iP4200	
iP4000	
iP3300	
iP3000	
iP2200	
iP1700	
iP1600	
iP1500	
iP90	
i950	
i470D	
DELL	
All-in-One Photo Printer 922	
DYMO	
LabelWriter duo	
LabelWriter TwinTurbo	
LabelWriter 400 turbo	
LabelWriter 400	

LabelWriter 330 turbo	
LabelWriter 320	
LabelWriter 310	
EPSON	
Epson DX8400	
HP	
deskjet 5740	
deskjet 5650	
deskjet 5551	
deskjet 948C	
Photosmart 2610	*3, *4, *5
PSC 2450	*3, *4, *5
PSC 2355	*3, *4, *5
PSC 1315	*3, *4, *5
OfficeJet 6210	*1, *3
Konica Minolta	
PagePro 1390MF	
PagePro 1380MF	
magicolor 2480MF	
Lexmark	
Z810	
X5250	

*1 This model does not support PC fax function.

*2 An image data in a memory card cannot be read through "MP Navigator ", the utility attached to a MFP.

*3 Scanning operation cannot be carried out in the scanning software of the printer attachment CD.

*4 Scan can be carried out in the scanning wizard (WIA) for OS preinstallation.

*5 Scan can be carried out by the TWAIN driver.

*6 Please use firmware version 1.1.0 or later.

*7 Please connect MFP to PC directly when you install attached software "MP Navigator Ver3.0.0".

Scanner

Supported OS

Windows 2000, Windows XP

Scanner model	Note
Avision Simplex Color AV121	
Avision AV210C2	
Avision AV220C2	
Avision AV3850SU	
CANON CanoScan LiDE500F	
CANON CanoScan LiDE80	
CANON CanoScan LiDE50	
CANON CanoScan LiDE40	
CANON CanoScan 5200F	
CANON CanoScan 5000F	
CANON CanoScan D1250U2	
EPSON GT-9400UF	
EPSON GT-8200U	
EPSON GT-7700U	
EPSON GT-7400U	
EPSON GT-F600	
EPSON GT-F550	
EPSON GT-F500	
EPSON GT-X800	
Fujitsu fi-5530C	
HP ScanJet 7800	
HP ScanJet 8270	
Kodak i40 Scanner	
Kodak i30 Scanner	
Mikrotek ScanMaker 5950	
Panasonic KV-S3065CW	

Panasonic KV-S3065CL	
PFU fi-5110EOX2	
Xerox DocuMate 262	*1

*1 Please make sure to use at least OneTouch 4.0.6.1013 if you want to use the scan button.

Storage

Supported OS

Windows 2000, Windows XP

Storage model	Note
Digital camera	Canon IXY DIGITAL 30 *1
	Canon IXY DIGITAL L
	Fujifilm FinePix F440
	Panasonic LUMIX DMC-FX7
	Panasonic LUMIX DMC-F1
USB memory	BUFFALO ClipDrive RUF-C32M
	IO DATA EDP2-512M *1
	IO DATA EDP-128M *1
	Hagiwara SYS-COM HUD-512PJ
Card reader	BUFFALO MCR-C8/U2
	BUFFALO MCR-8U/U2
	Panasonic BN-SDCGP3
	SONY MSAC-US30
	TDK U2RW01CMS
Audio player	Apple iPod 20GB SpecialEdition [M9787J/A]
HDD	BUFFALO HD-250U2
	BUFFALO HD-160U2
	BUFFALO HD-HB250U2
	BUFFALO HD-PH80U2/BST
	BUFFALO HD-P80U2/UC
	BUFFALO HD-P40U2/UC
	BUFFALO DUB2-B120G
	DViCO M3000U
	EPSON P-2000
	IO DATA HDH-U250S
	IO DATA HDH-U250
	IO DATA HDH-U160S
	IO DATA HDH-U160
	IO DATA HDA-iU120
	IO DATA HDW-UE320
Logitech LHD-PBH40U2	
DVD-R/RW	BUFFALO DVSM-DH516U2 *2
	BUFFALO DVM-RDH16U2 *2
	IO-DATA DVR-UM16A *2
	IO-DATA DVR-iUN8WR *2
	IO-DATA DVR-iUN4 *2
	Panasonic LF-P767C *3
USB HUB	Corega CG-UHUB4P *4
	ELECOM U2H-K4BSV *4
	ELECOM U2H-S4SSV *4
	GreenHouse GH-UHC204BW *4
	LOAS UH-1104W *4
	LOAS UH-224SL *4
	LOAS UH-204GM *4
	RIX USB-003-BS *4
	RIX USB-002-BL *4
SIGMA SHBH-4SV *4	

*1 An attached utility cannot be used.

*2 A write-error or a bit error may occur depending on the network condition.

*3 A diagnostic tool for bus power that is attached to DVD-R/RW is not available.

*4 If an AC adapter is attached to a USB hub, please use it.

Smart Card Reader

Supported OS

Windows 2000, Windows XP

Smart Card Reader	Note
Reiner SCT cyberJack e-com USB	
Reiner SCT cyberJack pinpad USB	